

HABS
WASH
6-VANCO,
4A-

Historic American Buildings Survey

INDEX TO PHOTOGRAPHS

Vancouver Barracks, Chapel (Building No. 701)
McClelland and McLoughlin Roads
Vancouver
Clark County
Washington

HABS No. WA-206-A

John Stamets, photographer

December 1993

<u>HABS No.</u>	<u>Description</u>
-----------------	--------------------

- | | |
|-------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| WA-206-A-1 | Context view looking east down McClelland Road from corner of McClelland and McLoughlin Roads. North end of Chapel is on right. Barracks Building No. 987 is on left. Other barracks are partially visible in distance |
| WA-206-A-2 | Elevation view of front, or north side. |
| WA-206-A-3 | Perspective view shows north and west sides. |
| WA-206-A-4 | Elevation view of west side. |
| WA-206-A-5 | Elevation view of rear, or south side. Building No. 987, a barracks, is in background. |
| WA-206-A-6 | Elevation view of east side. |
| WA-206-A-7 | Elevation view of south end of east side. |
| WA-206-A-8 | Detail of chimney and roofline on east side includes middle and north end of east side. |
| WA-206-A-9 | Interior view of sanctuary as seen from foyer doors. |
| WA-206-A-10 | Interior view of sanctuary as viewed from stage. Includes rear balcony and stairs. |
| WA-206-A-11 | Interior view of stairs leading to balcony. |
| WA-206-A-12 | Interior view of room in SE corner of building and behind stage. Camera is pointed SW. |
| WA-206-A-13 | Photocopy of a 1937 plan view drawing of the Basement, First Floor and Balcony of Building No. 701, the Chapel. The HABS film is a high-contrast 8x10 ⁿ litho negative made from a document in the collection of Vancouver Barracks, Vancouver, WA. |